



**Mat. Stal Ck 15**

Gwint d x P	SW	L=2 x d
TR 10 x 2	17	15
TR 10 x 3	17	15
TR 12 x 3	19	18
TR 14 x 3	22	21
TR 14 x 4	22	21
TR 16 x 4	27	24
TR 18 x 4	27	27
TR 20 x 4	30	30
TR 22 x 5	20	33
TR 24 x 5	36	36
TR 26 x 5	36	39
TR 28 x 5	41	42
TR 30 x 6	46	45
TR 32 x 6	46	48
TR 36 x 6	55	54
TR 40 x 7	65	60
TR 44 x 7	65	66
TR 48 x 8	75	72
TR 50 x 8	75	75
TR 60 x 9	90	90
TR 70 x 10	90	105